

Read this package insert carefully before use

Hypochlorite Solution

REF 04-4012_R

APPLICATION

RUO For Research Use Only. Not for use in diagnostic procedures.

Hypochlorite Solution is intended to reduce protein in sample pathway of flow cytometers.

KIT COMPONENTS

Packing contains the following reagents:

• 250 ml Hypochlorite Solution

Hypochlorite Solution is an aqueous solution. For further information refer to its Safety Data Sheet(s).

Component	Concentration [g/l]
Sodium Hypochlorite	< 40
Sodium Hydroxide	< 5

PRINCIPLE OF EXAMINATION METHOD

Reagent is used to remove samples residues in the flow cytometer. For further information refer to the Instructions for Use (IFU) of the flow cytometer.

ADDITIONAL REQUIRED EQUIPMENT

A clean sample tube compliant to the flow cytometer. For further information refer to the IFU of the flow cytometer.

STORAGE AND STABILITY

Storage

Store at 18 - 30 °C, do not freeze or expose to elevated temperatures.

Shelf life

Please refer to the expiration date on the bottle label.

Shelf life after first opening

Hypochlorite Solution will be stable until expiry date.

HAZARD AND PRECAUTIONARY STATEMENTS

For further information refer to the Safety Data Sheet(s). Find Safety Data Sheets to our products at www.sysmex-partec.com

Hazard pictogram(s)



GHS05: Corrosive

Signal word

Danger

Hazard statement(s)

H314 Causes severe skin burns and eye damage.

Precautionary statement(s)

P264	Wash thoroughly after handling.
P280	Wear protective gloves/eye protection.
P303+P361 +P353	IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water [or shower].
P305+P351 +P338	IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.
P310	Immediately call a POISON CENTER/doctor.
P501	Dispose of contents/container to a facility in accordance with local and national regulations.

PERSONAL PROTECTIVE EQUIPMENT

When using the reagent(s) make sure to wear suitable PPE (gloves, eye protection and chemical work clothing). For additional information please consult Safety Data Sheet(s).

INDICATIONS OF DETERIORATION


Do not use Hypochlorite Solution after appearance of any kind of turbidity or contamination. For questions regarding to the performance or quality of the product received, please contact your local Sysmex representative.

DISPOSAL PROCEDURE

Disposal procedure should meet requirements of applicable local regulations.



MANUFACTURER



Am Flugplatz 13 02828 Görlitz

Germany

Fon	+49 3581 8756 - 0
Fax	+49 3581 8746 - 70
E-mail	info@sysmex-partec.com
Web	www.sysmex-partec.com

CE

SYMBOLS



Number Batch code

Reference

Manufacturer Temperature



LOT

Use by



Consult instructions for use



CE-mark

limit

Rev.: 001 Rev. date: 01.08.2019 Doc. No.: 04-4012_R PAI EN CN 1106